

QUALITY MANAGEMENT PROCEDURE

Proc. N°

MIP 08

Rev.

02

DOCUMENT TITLE:

LIST OF INSPECTION ACTIVITIES INCLUDED IN THE FLEXIBLE SCOPE

REVISION HISTORY

REV	DATE	ISSUED BY	REVIEWED BY	APPROVED BY
00	18 July 2024	D. Brambilla	C. Bruseghini	E. Satta
01	11 September 2024	D. Brambilla	C. Bruseghini	E. Satta
02	22 January 2025	D. Brambilla	C. Bruseghini	E. Satta

QUALITY MANAGEMENT PROCEDURE

Proc. N°
MIP 08

Rev.
02

Field	Range	Stage	Requirements
- Agricoltura, prodotti alimentari e loro derivati	- Ispezione documentale - Ispezione Visiva - Ispezione sulla produzione/processo	- Produzione - Collaudo - Pre-spedizione - Carico - Scarico - Post-Spedizione	• Proc. SDP 11 rev. 07 • Specifiche del Cliente
- Prodotti industriali	- Ispezione documentale - Ispezione Visiva - Ispezione sulla produzione/processo	- Produzione - Collaudo - Pre-spedizione - Carico - Scarico - Post-Spedizione	• Proc. SDP 11 rev. 07 • Specifiche del Cliente
- Prodotti medicinali e cosmetici	- Ispezione documentale - Ispezione Visiva - Ispezione sulla produzione/processo	- Produzione - Collaudo - Pre-spedizione - Carico - Scarico - Post-Spedizione	• Proc. SDP 11 rev. 07 • Specifiche del Cliente
- Materie prime secondarie e scarti di lavorazione	- Ispezione documentale - Ispezione Visiva - Ispezione sulla produzione/processo	- Produzione - Collaudo - Pre-spedizione - Carico - Scarico - Post-Spedizione	• Proc. SDP 11 rev. 07 • Specifiche del Cliente

Field	Range	Stage	Requirements
- Agricultural, food products and their derivatives	- Documental Inspection - Visual Inspection - Production/process Inspection	- Production - Testing - Pre-shipment - Charging - Unloading - Post-shipment	• Proc. SDP 11 rev. 07 • Client Specification
- Industrial products	- Documental Inspection - Visual Inspection - Production/process Inspection	- Production - Testing - Pre-shipment - Charging - Unloading - Post-shipment	• Proc. SDP 11 rev. 07 • Client Specification
- Medicines and cosmetic products	- Documental Inspection - Visual Inspection - Production/process Inspection	- Production - Testing - Pre-shipment - Charging - Unloading - Post-shipment	• Proc. SDP 11 rev. 07 • Client Specification
- Secondary raw materials and processing waste	- Documental Inspection - Visual Inspection - Production/process Inspection	- Production - Testing - Pre-shipment - Charging - Unloading - Post-shipment	• Proc. SDP 11 rev. 07 • Client Specification

	QUALITY MANAGEMENT PROCEDURE	Proc. N° MIP 08 Rev. 02
--	-----------------------------------------	------------------------------------------------

1. CUSTODIAN

The Quality Manager is the custodian of this procedure.